X30 Monitor Training

Module 1 : IsoBridge Updates

Preface-Step 1

- **It is recommended to Update the X30 first, and the IB-1 second.**

- Start the process by powering off the X30 system. This will turn the IsoBridge off, the blue LED light will be off when the system is off.

- You will need a USB stick with the correct IsoBridge Update file (Version 4.04.06) which can be provided by a Morris representative.

STEP 2

- Disconnect the 4 pin ECU connector from the CAN input on the IB-1.

STEP 3

- Insert your USB stick into the IB-1 port.
- Then power on the X30 monitor, the IB-1 will power on also.

Step 4

- The data transfer will start; you will see the data stick blinking and the blue Led indicator on the IB-1 flashing.

- **Pay attention to the Blue led indicator after several minutes it will flash steadily and then will turn off.**

STEP 5

- **When the led is OFF quickly remove the data stick. You only have around 5 seconds to remove the stick.**

- Then let the IB-1 run the program for around 3-5 mins. The blue LED will be blinking.

Step 6

- Power off the X30 monitor, which will turn everything off.

- Then, reconnect the Can1 plug and power on the X30 system.

STEP 7

- Check the firmware version on the X-30. (See chapter 20-2 of Operator's Manual)

- In this case, the correct version was 2.07-r1

- Print and attach a label with the firmware version and date to the unit.

MORRIS

We hear you.