



9 SERIES TRAINING

Module 5 : Double Shoot Collectors

PURPOSE

- The flapper can break out if it is not maintained properly.



MAINTENANCE

- During PDI and pre-season checks, the set screws on the flapper control rod need to be reviewed.
- This is to make sure they don't move and are set properly.
- ICT control rods have been altered so that they don't move as showed in the picture on the right.



